

Galloping Goose No. 5 Maintenance Log

DATE	JOB	REMARKS	NAME
Aug 11, 2014	R+R Cal Oil (fuel filter)	ACQUIST P/N 86032 (5/16" nipple)	Brandell
Aug 11/14	R+R Air cleaner	Used 5W-30 oil. Oil was worn (fluo)	Beringer
Aug '14	Disassembled Rear Axle	wheels of front truck. ^{Some} never wear on right front bushing was visible. Also, the measurement between the space on the rear axle was ^{1/4"} about 1/2" wider than on the front axle. Also discovered that on the rear axle, the lower ^{part of the} left & right bushings were reversed. Also, there was only a small wad of packing in the lower part of each bearing.	Law Math
	Reassembled	Reassembled the rear axle and wheels of the front truck. Jack Based on advise from Dave Nicholson, the Hattaway bushings are doing okay. He recommended enough packing in the lower part to drive it well in contact with the axle, which Jack did on reassembly. The mismatched lower bushings were mated with the correct upper bushings.	Jack Hattaway

