

Galloping Goose #5 - Maintenance - Tune-Up Data.

Item	Detail	Part Number
Points and Condenser for GMC 361 CID inline 6 cyl. truck eng		NAPA CS763A
Point Setting	0.020	
Valves Set at	.012 Hot both Intake and Exhaust.	
Firing Order Clockwise Rotation on Distributor	1 4 2 6 3 5	Note: not the sequence stamped on the Engine or Manifold
Spark plugs		Autolite 86 NGK 5858 (VRB?)
Spark Plug gap	0.035 per GG#5 Maintenance notes	Per GMC Tune up data Berfore 1946 0.025" After 0.030"
Note: The New Extra Voltage Regulator has been Polarized.		
Fuel Filter in line type with 5/16th" nipples		Duralast FF3424 Carquest 86032 (specify with 5/16" nipples)
Rotor		NAPA #RR83
Rotor (distributor) Cap		NAPA #RR95
Fuel Additive for Unleaded Gas	Lead substitute 1 pt./30 gal tank	
Air liquid separator	Speedaire with 1/4" comp. fittings	6ZC24 (NAPA says it's from Grainger - no longer available 2/2015)